

Tanker Damaged in Collision With Ro/Ro in the Netherlands

A tanker collided Friday with a Grimaldi Lines vehicle carrier in the Westerschelde estuary in southern Netherlands near the border with Belgium.

Some grainy video shows the moment the tanker, identified as the Swiss-flagged **MT LEONARDO**, struck the **MV GRANDE AFRICA** reportedly at about 14:45 p.m.



The tanker is reported to have sustained severe damage in the collision and has been taken to Antwerp.

A photo the vessel posted here shows some damage to port side of the tanker. The **MV GRANDE AFRICA** was not badly damaged in the collision, reports say. There have been no reports of pollution or injuries.

Source : gCaptain

Photo : Crew Leonardo